OUT5365<sup>8</sup>

TOPS	E CR E T 261951Z	ा हा क्राया । विकास का स्थापन
PRIORITY	40// IIII 00 00	25 <b>X</b> 1
DEALIST	1964 JUN 26 21 04 Z	2 9 JUN 19
SUBJ: 1	12-B CAMERA SYSTEM	HFS T
	IMPR Hatte many many many many	CJS
	HERE HAVE BEEN TWO OPERATIONAL MISSIONS UTILIZING THE 112-B	
CAMERA S'	YSTEM. THESE TWO MISSIONS (W224A AND W234A) HAVE BOTH BEEN	PINS
LACKING 1	IN THE TRANSMITTAL OF THE PROPER INFORMATION FOR THE EXPLOIT	
	THE PHOTOGRAPHY.	
2. LA	ACK OF THIS INFORMATION CAN BE TRACED TO SEVERAL DIFFERENT	Grace (File
A•	THE FAILURE OF THE DATA BLOCK IN THE CAMERA.	
₿.	THE FAILURE OF THE 112 CONFIGURATION REPORT	25X1
	TO ARRIVE AS IT SHOULD HAVE.	7
C.	THE FILING OF INCOMPLETE INFORMATION IN THE MISSION WEATHER	
	AND TO A CO. THE CO.	25 <b>X</b> 1

D. THE FILING OF AN INCOMPLETE PILOT'S LOG.

AND TRACK REPORT

3. THE FAILURE OF THE DATA BLOCK DECREASES THE VALUE OF THE FILM, SINCE NO DETERMINATIONS OF CYCLE RATE, SCAN RATE, OR OPERATING MODE CAN BE PRODUCED WITHOUT THE DATA BLOCK. THESE ITEMS ARE INPUTS TO OUR COMPUTER PROGRAMS AND THEREFORE OF PRIMARY IMPORTANCE. THE CAMERA SERIAL NUMBERS WERE NOT ON THE FILM AND THEREFORE NO DETERMINATION OF CAMERAS COULD BE MADE. THE SERIAL NUMBERS SHOULD HAVE BEEN CARRIED SEVERAL PLACES, BUT WERE NOT AVAILABLE FROM ANY SOURCE, SO THE PROPER FOCAL

25X1

Approved For Release 2007/12/10 : CIA-RDP78B04558A001700020002-0

decreasification downstrating and Exemple from automatic

LENGTHS AND CALIBRATION ANGLES WERE NOT AVAILABLE FOR OUR COMPUTER PROGRAMS. DUE TO THE LACK OF PROPER DATA, NO COMPUTER ANSWERS WERE AVAILABLE FOR THESE TWO MISSIONS.

SHOULD CONTAIN MUCH OF THE MISSING INFORMATION BUT
WAS NOT AVAILABLE FOR THE TECHNICAL EVALUATION AND EXPLOITATION OF
THE FILM.

25X1

25X1

25X1

- FOR SEVERAL ROUTE SEGMENTS. THIS LACK OF ALTITUDE DATA COMPLETELY

  LIMITS THE USEFULNESS OF THE FILM SINCE NO DETAILED MEASUREMENTS MAY

  BE MADE WITHOUT THIS DATA.
- 6. THE PILOT'S FLIGHT LOG WAS NOT COMPLETED AND THE INFORMATION THAT COULD HAVE BEEN GLEANED FROM THIS SOURCE WAS NOT AVAILABLE TO THE INTERPRETATION TEAMS.
- 7. THE INFORMATION IS VITAL TO THE PROPER EXPLOITATION OF THE FILM; THIS ALSO HOLDS TRUE FOR THE DATA BLOCK INFORMATION AND THE PILOT'S LOG.
- 8. IF ANY OF THESE SOURCES OF INFORMATION FAIL, THE VALUE OF THE FILM FOR DETAILED ANALYSIS DECREASES. WITH THE FAILURE OF SEVERAL SOURCES OF INFORMATION AS OCCURRED ON MISSIONS W224A AND W234A THE INTELLIGENCE POTENTIAL OF THE FILM IS SHARPLY CURTAILED AND BECOMES OF VALUE ONLY TO MAKE GENERAL DETERMINATIONS. NO SPECIFIC MEASUREMENTS OR ANALYSIS IS POSSIBLE WITHOUT THE PROPER INPUT PARAMETERS FOR THE COMPUTER PROGRAMS OR OTHER COMPUTATIONAL METHODS.

TOPSECRET

/END OF MESSAGE/